



(https://life-adsorb.eu/sites/default/files/styles/img_1280x768_image_scale_crop_main/public/media/images/capture_decran_2025-07-28_104705.png?itok=1h5Nnowc)

ENTRETIEN

Dam repaired, system optimized

Successful rehabilitation of the dike between the two filters: optimal operation restored!

Published on 23 October 2025

During the last mowing and maintenance operation, a failure was detected in the central separation between the two filters. This dike, which had partially subsided, was causing continuous overflows from one filter to the other, compromising the proper functioning of the installation.

To address this issue, rehabilitation work was carried out in June to rebuild an effective separation between the two filters.

Thanks to this intervention, the overflows have stopped. The system is now operating optimally, ensuring greater efficiency and long-term durability.